## PROJECT REPRESENTATIVE'S DAILY REPORT

**Pg**. 1 **Report No**. 020

**Date**: 2014-09-15 **Day**: Monday

**Architect**: Kang Associates

**Project**: Renovation and Addition to Tewksbury Town Hall

**OPM**: CBI Consulting Inc. **Clerk of the Works**: Jeff Barnes

**Contractor**: G.V.W., Inc.

Weather: 7:30 am: cloudy Noon: some clouds 3:00 pm: partly cloudy

**Temperature**: **7:30 am**:  $40^{\circ}$  **Noon**:  $59^{\circ}$  **3:00 pm**:  $62^{\circ}$ 

Superintendent: Vinnie Bomal

| PERSONNEL<br>COUNT | Spec<br>Section    | Contractor             | Trade                 | Foreman | Journeymen | Helpers | Total |
|--------------------|--------------------|------------------------|-----------------------|---------|------------|---------|-------|
| General            | Div. 06<br>Div. 04 | GVW                    | Carpentry<br>Masonry  | 1 0     | 0          | 5       | 6     |
| Contractor:        | 09 90 00           |                        | Painting Painting     | 1       | Õ          | 1       | 2     |
| Subcontractors:    | 02 08 00           | A & J Demo<br>Services | Asbestos<br>Abatement | 0       | 0          | 0       | 0     |
|                    | 26 00 00           | Griffin Electric       | Electrician           | 0       | 0          | 0       | 0     |
|                    | 22 00 00           | Lapan<br>Mechanical    | Plumber               | 0       | 0          | 0       | 0     |
|                    |                    |                        |                       |         |            |         |       |
|                    |                    |                        |                       |         |            |         |       |
|                    |                    |                        |                       | 2       | 0          | 6       | 8     |
| Total:             |                    |                        |                       |         |            |         |       |

## DAILY REPORT

## **Activities Today:**

- 1) GVW is in the process of demolishing the inside face of the exterior basement walls and other debris from the basement.
- 2) GVW started scraping and prepping the cupola.
- 3) GVW removed the radiators from the lobby.

Copies to: Richard Montuori, Town of Tewksbury Ed Johnson, Town of Tewksbury

Steve Sadwick, Town of Tewksbury Wayne Lawson, CBI

Jenne dos Santos, CBI Kaffee Kang, Kang Architects

## PHOTO INDEX



Photo showing interior demolition of the basement walls.



Photo showing interior demolition of basement.



Photo of interior demolition of basement.



Photo showing radiators removed from lobby.



Photo showing painters scraping the cupola.



Photo showing work on the cupola.



Photo showing extent of work on cupola after first day.